
















## Layout Parameters

Control Edit Show Utilities View Help

Ok	<b>Axis Lines</b> <input checked="" type="checkbox"/> X <input type="checkbox"/> <input checked="" type="checkbox"/> Y <input type="checkbox"/> <input checked="" type="checkbox"/> Z <input type="checkbox"/>	<b>Simulation Locations</b> <input checked="" type="checkbox"/> Primary Target Point <input type="checkbox"/> <input checked="" type="checkbox"/> + Horiz <input type="checkbox"/> <input checked="" type="checkbox"/> + Vert <input type="checkbox"/> <input checked="" type="checkbox"/> - Horiz <input type="checkbox"/> <input checked="" type="checkbox"/> - Vert <input type="checkbox"/>	<b>Simulation Objects</b> <input checked="" type="checkbox"/> Environment <input type="checkbox"/> <input checked="" type="checkbox"/> Enc <input checked="" type="checkbox"/> Splr <input checked="" type="checkbox"/> Port <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>			           
----	---	--	--	--	---	---



235.8 X,Y,Z Pos 2.0000 6.0000 0.0000 in X,Y,Z Deg 0.00 0.00 0.00

187% Abs Rel System Guide 12 Horz Polar F= 3.84K -N/A- -N/A- Left Right